

TABLE OF FILAMENT APPLICATIONS

FILAMENT GROUP	FILAMENT NAME	EXTRUSION TEMP.	PLATFORM TEMP.	CHAMBER TEMP.	ENDURANCE	DURABILITY	FLEXIBILITY	EASE OF PRINTING	SUPER POWER	APPLICATION
BASIC FILAMENTS	ABS-42	235-255°C	80-110°C	60-70°C					Durability and a smooth finish	Final parts and prototyping
	ASA-39	240-260°C	80-110°C	60-70°C					Resistant to UV radiation	Elements exposed to weather conditions
	PET-G-32	230-250°C	60-90°C	without a heated chamber					Approved for contact with food	Final parts for special use
	PLA-36	180-210°C	25-60°C	without a heated chamber					Biodegradable	Prototyping
	PLA-WOOD	180-210°C	25-60°C	without a heated chamber					Wooden finish	Prototyping
	Ultrafuse® ABS Fusion+	240-260°C	80-110°C	55°C					Improved layer bonding	Geometrically complex models
TECHNICAL FILAMENTS	PC-ABS-47	250-280°C	100-130°C	60-70°C					Increased temperature resistance	Final parts
	TPU-93A	210-230°C	40-50°C	without a heated chamber					Flexibility and chemical resistance	Final parts for special use
	PA-6/66HD	240-260°C	0-80°C	without a heated chamber					Abrasion resistance	Final parts
	PA-12	250-290°C	0-100°C	50°C					Mechanical resistance	Final parts with increased resistance
	3DXSTAT™ ESD-PETG	230-260°C	60-90°C	without a heated chamber					Electrostatic resistance	Final parts used in electronics
	PP	200-220°C	0-110°C	without a heated chamber					Light and flexible, chemically and mechanically resistant	Elements requiring chemical and mechanical resistance

TABLE OF FILAMENT APPLICATIONS

FILAMENT GROUP	FILAMENT NAME	EXTRUSION TEMP.	PLATFORM TEMP.	CHAMBER TEMP.	ENDURANCE	DURABILITY	FLEXIBILITY	EASE OF PRINTING	SUPER POWER	APPLICATION
SPECIALIST FILAMENTS	CF-PA-12	250-290°C	40-100°C	50-70°C	●●●●●●●●	●●●●●●●●	●●●●●●●●	●●●●●●●●	Temperature resistance	Final parts exposed to extreme working conditions
	THERMEC™ZED	300-330°C	100-130°C	70°C	●●●●●●●●	●●●●●●●●	●●●●●●●●	●●●●●●●●	Chemical resistance	Elements exposed to temperatures up to 200 ° C
	XSTRAND™ GF30-PA6	250-290°C	40-100°C	50-70°C	●●●●●●●●	●●●●●●●●	●●●●●●●●	●●●●●●●●	Mechanical resistance, low conductivity	Final parts for special use
	PEKK-A	370-380°C	110-130°C	60-80°C	●●●●●●●●	●●●●●●●●	●●●●●●●●	●●●●●●●●	Extreme mechanical strength	Products exposed to extreme working conditions
	PMMA	240-270°C	60-120°C	40-60°C	●●●●●●●●	●●●●●●●●	●●●●●●●●	●●●●●●●●	UV radiation transmittance, transparency	Glass replacement
	ABS V0	235-255°C	80-110°C	60-70°C	●●●●●●●●	●●●●●●●●	●●●●●●●●	●●●●●●●●	Self-extinguishing, resistant to fire	Elements exposed to fire
	PET-G Carbon	220-260°C	60-100°C	without a heated chamber	●●●●●●●●	●●●●●●●●	●●●●●●●●	●●●●●●●●	PET-G with increased impact strength	Prototyping test models
	ABS FC	235-255°C	80-110°C	60-70°C	●●●●●●●●	●●●●●●●●	●●●●●●●●	●●●●●●●●	Biocompatibility, food contact possible	Medicine, food industry
	ABS-ESD	230-250°C	80-100°C	60-70°C	●●●●●●●●	●●●●●●●●	●●●●●●●●	●●●●●●●●	Antistatic, durability	Electrical industry, housings of electrical components
	PP-C	220-260°C	40-80°C	without a heated chamber	●●●●●●●●	●●●●●●●●	●●●●●●●●	●●●●●●●●	Low hygroscopicity, chemically inert	In a chemical environment and in the needs of mechanical strength
SUPPORT FILAMENTS	HIPS-20	220-240°C	70-110°C	without a heated chamber	●●●●●●●●	●●●●●●●●	●●●●●●●●	●●●●●●●●	Breakaway support material	Basic support material
	ODS-20	230-240°C	80-110°C	50-70°C	●●●●●●●●	●●●●●●●●	●●●●●●●●	●●●●●●●●	Soluble in alkaline solution	Support material for industrial filaments
	PVA-20	200-230°C	50-90°C	without a heated chamber	●●●●●●●●	●●●●●●●●	●●●●●●●●	●●●●●●●●	Water-soluble	Support material for PLA and Nylon